# **Preliminary - For Review Only**

### NAVSEA STANDARD ITEM

FY-06

#### 1. SCOPE:

1.1 Title: Passive Countermeasures System (PCMS) Material Repair/ Installation Requirements; accomplish

### 2. REFERENCES:

- 2.1 Standard Items
- 2.2 RIM 05T1-99, Passive Countermeasures System (PCMS) Repair/Installation Methods
- 2.3 PHS&T 05T1-06, Passive Countermeasures System Packaging, Handling, Storage and Transportation Plan

#### 3. REQUIREMENTS:

- 3.1 Install new PCMS material in accordance with 2.2 and 2.3.
- 3.1.1 Personnel involved in PCMS material installation, including surface preparation, material application, final painting, and quality assurance shall be trained and certified in accordance with Section B.3 of 2.2.
- 3.1.2 Accomplish the requirements of Sections B.4 and B.5 of 2.2 for material control and material disposition.
- 3.1.3 Accomplish additional PCMS material handling and storage requirements in accordance with 2.3.
- (V)(G) "ENVIRONMENTAL REQUIREMENTS"
- 3.1.4 Verify the environmental requirements of Section C.1 of 2.2 are met prior to application of primers, tiles, caulking, and paint.
- 3.1.5 Accomplish surface preparation of surfaces receiving new PCMS material in accordance with Section C.2 of 2.2.

1 of 2 ITEM NO:  $\frac{009-78}{\text{FY}-06}$ 

## **Preliminary - For Review Only**

- 3.1.6 Preserve surfaces receiving PCMS material in accordance with Section C.2.3 of 2.2.
  - 3.1.6.1 Accomplish the requirements of 009-32 of 2.1.
- 3.1.7 Accomplish preliminary cleaning, abrasion, and final cleaning of primed surfaces in accordance with Section C.4.4 of 2.2 for non-Pressure Sensitive Adhesive (PSA) tiles, or Section C.4.5 of 2.2 for PSA tiles.
- (V)(G) "WELD FAIRING"
- 3.1.8 Verify the fairing of weld seams is in accordance with Section C.3 of 2.2.
- 3.1.9 Install new PCMS material in accordance with Section C.4 of 2.2.
  - 3.1.9.1 Template from existing shipboard conditions.
- 3.1.10 Caulk all seams and exposed edges in accordance with Section C.5 of 2.2.
- (V)(G) "FINAL INSPECTION"
- 3.1.11 Accomplish a final inspection of newly installed PCMS material to verify correct installation.
- 3.1.12 Accomplish surface preparation and preservation for topcoat of new PCMS material in accordance with Section C.6 of 2.2.
- $\it 3.2$  Accomplish the requirements of 009-32 of 2.1 for new and disturbed surfaces.
- 4. NOTES:
  - 4.1 None.

2 of 2 ITEM NO:  $\frac{009-78}{\text{FY}-06}$